

**INDEPENDENT VOLVO
SERVICE**

1401 THIRD ST. N.W.
ALBUQUERQUE NM 87102
ALBUQUERQUE NM 87102

(505) 247-9771

ivs@lobo.net

Estimate: **33964** 2/18/2009

AUTO SHOPPE IMPORTS

6616 Central Ave. Se
Albuquerque NM 87108

02182009 (505) 250-1120 p

**2001 Volvo S60T License: 2705/7848 Odometer: 61331 Vin: YV1RS58D812007848
B5244T3 AW55-50/51SN ABS PLATINUM GREEN**

PRESALE INSPECTION AND BASIC MAINTENANCE -

Labor performed on this job:

Labor 1 Labor Rate: \$90.00 \$90.00

INSPECT VEHICLE IN ORDER TO DETERMINE SERVICE
NEEDS BEFORE SALE

8

Parts: \$0.00
Labor: \$90.00
Job Subtotal: \$90.00

SERVICE WORK

Labor performed on this job:

Labor 2.3 Labor Rate: \$90.00 \$207.00

Replace spark plugs, left rear sway bar link, cabin air filter
and alternator voltage regulator. Service transmission.
Check fault codes: none found

8

Parts required on this job:

SPARKPLUG, BOSCH 5 \$1.99 \$9.95
SUPER 850, 960, 90,
C70, S/V70 -0

FILTER, FRESH AIR 1 \$35.58 \$35.58
CABIN S80 -06, V70
01+, S60, XC9

LINK ROD, SWAYBAR 1 \$53.67 \$53.67
REAR V70 01-07, S60 -
08, S80 -06

VOLTAGE REGULATOR 1 \$138.92 \$138.92

TRANSMISSION OIL 1 \$69.34 \$69.34

Parts: \$307.46
Labor: \$207.00
Job Subtotal: \$514.46

BRAKES, REAR WITH MACHINED ROTORS AND PADS

Labor performed on this job:

Labor 1.6 Labor Rate: \$90.00 \$144.00

Test drive in an attempt to duplicate customer complaint, if any. Examine wheel brakes for wear and deterioration. Remove and machine rotors, apply a non-directional swirl finish, reinstall. Examine calipers for leakage, clean and lubricate them as needed. Treat brake pad friction surfaces with BG brand noise control compound and lubricate pad backing surfaces with copper base antiseize. Reassemble torquing all threaded hardware and test drive to verify repairs.

8

Parts required on this job:

MACHINE BRAKE ROTOR 2 \$17.50 \$35.00

BRAKE PAD, REAR 1 \$71.74 \$71.74
S/V70 MID99-00 AWD,
S60, V70 01+, S80 -06

Parts: \$106.74

Labor: \$144.00

Job Subtotal: \$250.74

BRAKES, FRONT WITH NEW ROTORS AND PADS

Labor performed on this job:

Labor 1.8 Labor Rate: \$90.00 \$162.00

Test drive in an attempt to duplicate customer complaint, if any. Examine wheel brakes for wear and deterioration. Replace rotors with new. Examine calipers for leakage, clean and lubricate them as needed. Treat brake pad friction surfaces with BG brand noise control compound and lubricate pad backing surfaces with copper base antiseize. Reassemble torquing all threaded hardware and test drive to verify repairs.

8

Parts required on this job:

BRAKE PAD, FRONT 1 \$101.16 \$101.16

BRAKE ROTOR, FRONT 2 \$108.14 \$216.28
V70 01+, S60, S80 -06
(15"
WHEEL/286MM/11.25"
ROTOR)

Parts: \$317.44

Labor: \$162.00

Job Subtotal: \$479.44

BREATHER TANK RESEAL

Labor performed on this job:

Labor 5 Labor Rate: \$90.00 \$450.00

Check for positive pressure in sump, remove fuel rail and fuel injectors, remove intake manifold. Remove and clean breather box, replace seals and hoses as needed. Reinstall breather box, replace intake manifold gasket and reinstall intake manifold. Replace o-ring seals on oil dipstick tube, reinstall fuel injectors and fuel rail. Test run engine and recheck sump pressure, pressure is now negative.

8

Parts required on this job:

ORING, DIPSTICK TUBE 1 \$2.18 \$2.18

HOSE, OIL TRAP 1 \$6.56 \$6.56
LOWER RETURN

GASKET, INTAKE 1 \$14.50 \$14.50
MANIFOLD C/S70 99-04,
V70 99+, S80 5CYL,
S60, XC90 5CYL

Parts: \$23.25

Labor: \$450.00

Job Subtotal: \$473.25

EMISSION TEST(FLEET)

Labor performed on this job:

Labor 0.1882 Labor Rate: \$90.00 \$16.94

PERFORM BERNILILLO COUNTY EMISSION TEST

1

Parts: \$0.00

Labor: \$16.94

Job Subtotal: \$16.94

SHOP INFORMATION AND SUPPORT

Labor performed on this job:

Labor 0.43 Labor Rate: \$90.00 \$38.70

The information age has arrived and it is expensive. We currently spend in excess of \$1000 monthly for current Volvo service information and hardware associated with its use. Additionally, the myriad of items never invoiced i.e. Hardware, chemicals, cleaner and other supplies continue to escalate in cost. Our shuttle service is another new expense. This surcharge is to help recover a portion of these costs without increasing our labor rate. Thank you for your understanding and support.

9

Parts:	\$0.00
Labor:	\$38.70
Job Subtotal:	\$38.70

Estimate of Repair

Parts:	\$754.88
Labor:	\$1,108.64
Discounts:	(\$223.62)
Subtotal:	\$1,863.52
Tax:	\$0.00
Total:	\$1,639.90